

## **CASE STUDY**

# **Kerramerican Mine Site Hancock County, Maine**

**August 2010**

**Prepared by  
The Interstate Technology & Regulatory Council  
Mining Waste Team**

Permission is granted to refer to or quote from this publication with the customary acknowledgment of the source. The suggested citation for this document is as follows:

ITRC (Interstate Technology & Regulatory Council). 2010. *Kerramerican Mine Site, Hancock County, Maine*. Mine Waste Treatment Technology Selection Web. Washington, D.C.: Interstate Technology & Regulatory Council, Mining Waste Team. [www.itrcweb.org](http://www.itrcweb.org).

### **Acknowledgements**

The ITRC Mining Waste Team would like to acknowledge, Fred Lavalley, P.E., and Rob Peale, Project Managers, who completed the April 2008 Mine Waste Case Study Survey, from which the information in this case study is taken.

**TABLE OF CONTENTS**

1. SITE INFORMATION ..... 1  
    1.1 Contacts..... 1  
    1.2 Name, Location, and Description ..... 1  
2. REMEDIAL ACTION AND TECHNOLOGIES ..... 3  
3. PERFORMANCE..... 3  
4. COSTS ..... 3  
5. REGULATORY CHALLENGES..... 4  
6. STAKEHOLDER CHALLENGES ..... 4  
7. OTHER CHALLENGES AND LESSONS LEARNED ..... 4  
8. REFERENCES ..... 4

**LIST OF FIGURES**

Figure 1-1. Kerramerican Mine site ..... 2

## KERRAMERICAN MINE SITE, HANCOCK COUNTY, MAINE

### 1. SITE INFORMATION

#### 1.1 Contacts

Rob Peale  
Maine Department of Environmental Protection  
Telephone: 207-287-7679  
E-mail: [rob.n.peale@maine.gov](mailto:rob.n.peale@maine.gov)

Fred Lavallee  
Maine Department of Environmental Protection  
Telephone: 207-287-7677  
E-mail: [fred.c.lavallee@maine.gov](mailto:fred.c.lavallee@maine.gov)


Tracy Weston  
Project Manager  
Maine Department of Environmental Protection  
Telephone: 207-287-4862  
E-mail: [tracy.weston@maine.gov](mailto:tracy.weston@maine.gov)

#### 1.2 Name, Location, and Description

The Kerramerican Mine property is located along Route 15/176 in Blue Hill, Hancock County, Maine (Figure 1-1). The property is owned separately by DLM Associates and two private owners. The zinc and copper mine, which operated 1971–1977, was officially closed under an agreement with the Maine Department of Environmental Protection in 1981. An on-site access road forms the border between a mill process area and a waste disposal area on the property. The 53-acre waste disposal area consists of two former tailings ponds that have been covered with till and vegetation. The mill process area was formerly occupied by a hoist house, former service and concentrator buildings, foundations of former thickener units, and the headframe of a mine shaft. Three unnamed intermittent streams and Carleton Stream flow through the property. The property is bordered by Second Pond to the west, Carlton Stream to the south, and sparsely developed residential properties to the east and north.

In 1880, mining operations began in the area surrounding the property known as the Blue Hills Copper Mining District. Mine tailing wastes, such as copper slag from mining operations in the area, were disposed of along the shore of Second Pond. In 1964 and 1965, Black Hawk Mining Ltd. (Black Hawk) and Dennison Mines Ltd. of Toronto conducted extensive underground development of the ore body located directly beneath Second Pond. In 1971, Kerramerican Inc. (Kerramerican) constructed a mining facility on the property to produce zinc and copper from ore extracted from the mine located beneath Second Pond. The on-site streams were dammed to construct two tailings ponds. Reportedly, waste slag material from Second Pond was used in the construction of the Kerramerican facility and a dike separating the two tailings ponds. Between 1971 and 1977, operations at the property included the following: concentrating of raw material

by crushing and grinding ore, adding water to produce a fine slurry, and extracting mineral concentrates using an alkaline floatation process. Historically, reagents used in the milling process included unknown quantities of sodium sulfate, copper sulfate, lime, and other unknown reagents. Wastewater and tailings were discharged to the tailings ponds which served as primary and secondary settling basins. Water flowing from the tailings ponds was either recycled in the milling process or discharged to Carleton Stream. Storm-water runoff from the property is expected to enter on-site culverts or drainage ditches that discharge to Second Pond or Carlton Stream. In 1975, untreated mine tailings were released directly to Carleton Stream through broken pipes and valves.



**Figure 1-1. Kerramerican Mine Site.** Created with ESRI ArcView software using Microsoft Bing maps.

During a visit to the property in 1994, water with a pH of 2.8 was observed on the tailings pond and leading toward the auxiliary pond. Analytical results of source samples collected from the property in 1995 and 1999 indicated the presence of arsenic (As), silver (Ag), mercury (Hg), iron (Fe), cadmium (Cd), lead (Pb), zinc (Zn), copper (Cu), and chromium (Cr). Previous investigations of the property include periodic surface water sampling by the Environmental Improvement Commission and Maine Department of Environmental Protection (ME DEP) between 1971 and 1982; a Preliminary Assessment completed in 1995; a Site Inspection

completed in 1996; and an Expanded Site Inspection completed in 1999. Affected media at the site include soil, surface water and sediment, and groundwater.

## **2. REMEDIAL ACTION AND TECHNOLOGIES**

When mine operations ceased in 1977, the tailings ponds were covered with 12 inches of fill material and seeded. In 1981, Kerramerican covered all exposed mine tailings to prevent contamination of surface water and groundwater to comply with an administrative enforcement agreement made previously with ME DEP. After 1981, some of the soil covering the tailings deposits eroded to expose the waste tailings.

Recent monitoring suggested the tailings, below water table year-round, were not a major source of dissolved metals. However, exposed waste rock covering the 19-acre processing plant site was determined by modeling to release between 10,000 to 12,000 pounds per year of dissolved zinc to adjacent surface waters and lesser amounts of copper and other metals.

From 2007 to 2008, a multicomponent geosynthetic cover system was installed on the 19-acre processing plant site, considered the source of most dissolved metal exported from the site. A vegetative cover was applied to parts of the tailings impoundment where the original soil cover was damaged by erosion. Drainage improvements upgradient of the site diverted much of the runoff that previously passed through or ponded on the impoundment. Finally, modifications to an outlet structure created several acres of new wetlands, replacing areas impacted by the plant site cover system.

## **3. PERFORMANCE**

Effectiveness of the geosynthetic cover system and the soil cover will be evaluated with a minimum five-year semiannual groundwater and surface water sampling program downgradient of the covered plant site. However, no specific cleanup criteria are set because of other mining-related impacts to the watershed that have not been remediated. The five-year program began in 2009.

Additionally, routine inspections of remediated areas of the site are required to ensure that the caps and covers remain in place and are not compromised in any way. Future monitoring, inspections, and repairs will be paid for from a dedicated trust fund established by the Responsible Party.

## **4. COSTS**

The cost of the geosynthetic cover system and soil cover was \$7,000,000. Operation and Maintenance cost in 2005 dollars was \$1,800,000.

## **5. REGULATORY CHALLENGES**

Leaving large quantities of solid mine waste in place on-site presents issues with long-term stewardship (LTS). LTS can include the use of institutional control, restrictive and/or environmental covenants, and implementation of a monitoring and maintenance plan.

## **6. STAKEHOLDER CHALLENGES**

The project included transfer of liability to a third party who oversaw construction and will be responsible for long-term maintenance and monitoring.

## **7. OTHER CHALLENGES AND LESSONS LEARNED**

Public issues encountered during the remedial action included recreational access, truck traffic during construction, access and location of a fish fence at the outlet of the Second Pond to control unwanted species, and access to adjacent property for groundwater investigation and institutional controls.

## **8. REFERENCES**

U.S. Environmental Protection Agency. n.d. “Waste Cleanup and Reuse in New England Kerramerican Mine (Former), Blue Hill, Maine.”